
## HOPE Negative rake scrapers




For best results, grind to 89 deg then use a diamond file at 95 deg to force cutting burr on edge.



To sharpen from blunt, first grind the long bevel, then short bevel.

Use mandrel for the round tip to sharpen back edge.

For long lasting results, use a 300g (approx) diamond file at 85 deg to force cutting burr on the edge.



## HOPE Negative rake scrapers



These tools cut best around 1500-2000 rpm.

Cut on the centre line with the blades parallel.

I use a HOPE small quick release handle with the red head!

These tools are excellent for fine tuning of shape and leave a good finish.

Remember to keep re-applying an edge with your diamond file!

www.hopewoodturning.co.uk